



Many repairs and much rubbing down. Then drainage holes drilled into the base and covered with chicken wire, before bitumen is painted on the base (*inside and out*) followed then by the white undercoat



Its taking on a new look and almost seaworthy again – if it wasn't for the addition of the necessary drainage holes!!

